ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
8

Ward Name
Kodigehalli

Street ID
W0667, W0663, W0651, W0592, W0645, W0639, W0657, W

Street Name
NA, 1st Main Rd, 4th Crs, Pattanduru Agrahara Rd, 2nd Crs

Significant Landmark
BHADRAPPA LAYOUT

Segment No.
8/S-W0667/S044537

Total Length (m)
877.81

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	58.49	77.573673	13.048905	77.573638	13.048378	W0627	DEAD END
2	72.69	77.573509	13.049613	77.573622	13.048965	W0592	DEAD END
3	56.23	77.573850	13.049174	77.573716	13.049665	W0598	W0592
4	59.87	77.574064	13.049164	77.573968	13.049696	W0598	W0592
5	84.34	77.574375	13.049138	77.574220	13.049885	W0598	SWD
6	102.94	77.574708	13.049117	77.574531	13.050031	W0598	SWD
7	112.24	77.575019	13.049070	77.574831	13.050067	W0598	SWD
8	121.31	77.575284	13.049025	77.575083	13.050104	W0598	SWD
9	95.34	77.575493	13.048997	77.575314	13.049840	W0598	SWD
10	114.36	77.573981	13.050344	77.575035	13.050336	RI-S62	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to roads and drain at BHADRAPPA LAYOUT Surrounding in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
3900000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to roads and drain at BHADRAPPA LAYOUT Surrounding in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone

Job No. / Work Code
008-16-000003

Work Order No.
EE/BTP/BBMP/E-MPT/WO/196/2015-16

Work Order Date
03/02/2016

Period of Extention
90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
03/02/2016	02/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K R SANTOSH KUMAR		0.00

Phone No.	E-Mail ID
9448123078	

Field Inspection Details

Number of Trees	Any Other Information	Name
5		SRINIVASA MURTHY

Date of Inspection	Remarks
03/12/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0667, W0663, W0651, W0592, W0645, W

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	YARAPPA REDDY	03/12/2016	02/01/2017	COMPLETED
AEE	RAJANIKANTH MALLI	03/12/2016	02/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0667, W0663, W0651, W0592,

AE	SRINIVAS MURTHY	03/12/2016	02/01/2017	COMPLETED
AE	SRINIVAS MURTHY	03/12/2016	02/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0667, W0663, W0651, W0592,